
ASSEMBLY INSTRUCTION


Item NO: 1011

HARDWARE LIST			
NO.	PART	DESCRIPTION	Q'TY
Α		board	2
В		frame	4
С	(******	Transom 1	4
D	82	Transom 2	2
Е	 (B)	screw	24
F		allen key	1
G	*	nail	8
Н	٥	feet	8



Assembled process of the two tables are same, each part has a small one a big one.

step 1 step 2



step 3 step 4

